

POSITION	QTY	RESPONSIBILITY	COMPANY'S MINIMUM REQUIREMENTS
Safety Supervisor	2	<p>Responsible for field operation as SSHE Supervisor as of following:</p> <ul style="list-style-type: none"> • Support high risk activities for field operation as SSHE Supervisor at WORKSITE. <ul style="list-style-type: none"> • Drilling and Completion operation • Rigging up and down • Slinging equipment and operation • Cement mixing, pumping and circulating • Tubing cut/ punch and mechanical plug • Other related Drilling and Well services operation and logistics • Provide daily operation report and submit to COMPANY's representative and team • Ensure compliance with the COMPANY's SSHE standards, policies, and regulations • Support to develop and implement of technical safety guidelines, procedure and management system which comply with international standard, industry best practice and align with corporate direction i.e. risk assessment, process safety management, etc. • Participate in accident/incident investigation to analyses and provide advice on prevention measurement including with remedial actions to near misses or high potential incident related to technical safety and operation 	<ul style="list-style-type: none"> • Minimum seven (7) year experience related to Offshore operation consist of: Drilling, Completion, Well intervention, etc. • Minimum ten (10) year experience related to in oil and gas industry • Have experience of SSHE supervision for offshore operation and equipment • Good command in spoken and written English • Must be certified with basic safety such as T-BOSIET, H2S awareness, first aid, firefighting • Good knowledge of industry code, loss prevention process, safety analysis technique and legislation on SSHE aspect • Have strong leadership and good communication skills