

POSITION	QTY	RESPONSIBILITY	COMPANY'S MINIMUM REQUIREMENTS
Coiled Tubing (CT) Supervisor	4	<p>Responsible for field operation as CT Supervisor as of following:</p> <ul style="list-style-type: none"> • Develop and update operational procedures and setting standards under his scope of work. • Coordinate and control well operations, ensuring all planned and any unplanned activities are carried out in the most efficient manner. • Prepare work detailed program, summarize daily activities and complete final report after job finished. • Coordinate the overlap with concerned parties to carry out the jobs as per proposal. • Take overall responsibility for the condition of all equipment used in operations under limitation and ensure that equipment is properly rigged up and tested under pressure control principles and procedure. • Supervise and monitor the execution of specific operations as well as control and review well integrity in a safe manner. • Plan, control and ensure the optimization of technical integrity & maintenance of all asset wells and ensure that SSHE matters are in line with the company HSE-MS. • Conduct safety meeting, lead onsite JHA (Job Hazard Analysis) and toolbox meetings. Actively participate in morning operations meeting. • Plan and supervise all well integrity testing operation including function test of Surface Safety Valve (SSV) & Surface Control Subsurface Safety Valve (SCSSV) and wellhead maintenance. • Manage all available resources and workload under his accountabilities appropriately to ensure that objectives are achieved, and staff is fully utilized. • Diagnostic well's problems, support, troubleshoot and provide contingency plan to well services operations. 	<ul style="list-style-type: none"> • Minimum five (5) year experience with at least two (2) years in supervisory positions related to CT operation consist of: N2 lift, TBG cleanup, Acidizing, CT fishing, related 3rd party tools, etc. • Have experience of offshore operation and equipment • Experienced in supervising staff, contractors, and ensure adherence to Company rules & regulations and SSHE policy • Familiar with well services activities e.g. workover, perforations, well testing, well stimulation, slickline, wireline, well integrity, function test, and wellhead maintenance • Good command in spoken and written English • Good knowledge of computer applications • Must be certified with basic safety such as T-BOSIET, H2S awareness, first aid, firefighting. • Must be certified with IADC or IWCF well control (Intervention) certificate